

DRAINING VANDERHEYDEN RESERVOIR

The Town of Brunswick is once again draining the Vanderheyden Reservoir. We are under a directive from the New York State Department of Conservation to undertake the rehabilitation of the Vanderheyden Reservoir Dam and Spillway. We are draining the reservoir to survey the dam and bottom of the reservoir to more accurately estimate the materials required for reconstruction of the dam face. Last year experience tells us the dam will refill by the summer season.